From: <u>Josiam, Raji</u>
To: <u>"Matt Wickham"</u>

Subject: RE: Split Sampling and Oversight Plan for Field Work

Date: Wednesday, June 28, 2017 10:40:35 AM

Matt

As I was looking at the upcoming fieldwork I have a question. We were basing the split samples based on WRN-4 and WRN-5. Are you planning on doing all the off-property soil borings as well SB-47-SB-99? In that case we will be adding a few more split samples.

Raji Josiam

Remedial Project Manager

US EPA Region 6

1445 Ross Ave, Suite 1200, 6SF-RA

Dallas, TX 75202

Email: josiam.raji@epa.gov

Direct: 214-665-8529 Fax: 214-665-6660

Superfund: 1-800-533-3508



From: Josiam, Raji

Sent: Tuesday, June 27, 2017 2:55 PM

To: Matt Wickham

Subject: Split Sampling and Oversight Plan for Field Work

Matt

I had a call with EA Engineering and here is the plan we discussed.

Split Sampling Locations

Soil Borings - 3

 - 1) SB-106, 2) SB 109, and 3) SB-23 Replacement boring – samples will be taken from all three sampling intervals and samples will be analyzed for metals, VOCs, SVOCs, pesticides/herbicides, and TPH.

Monitoring Wells - 2

- 1) MW-7 and 2) Either MW-13, MW-14, or MW-6 (will be based on field PID readings in the saturated Zone)

Questions:

- For the off property locations SB-109 and SB-110 will your access agreement cover EPA's Contractors and TCEQ? If not we need access to cover them.
- For Monitoing Wells are you planning on collecting soil samples of the soil cuttings in addition to taking field PID readings of the cuttings?
- For SB-109 and SB-110, though not specified in the WRN, I am assuming the plan to take samples in all the three intervals, similar to other soil borings, correct?

Mark Kelly, is the geologist with EA Engineering and he will be conducting oversight during the duration of the field work. During the weeks two activities will be conducted at a time, a second EA Engineering field person may be onsite conducting oversight of field activities in the second location. This is the general plan and will be adjusted based on field conditions.

Please let me know if you have questions. Thanks.

Raji Josiam

Remedial Project Manager

US EPA Region 6

1445 Ross Ave, Suite 1200, 6SF-RA

Dallas, TX 75202

Email: josiam.raji@epa.gov

Direct: 214-665-8529 Fax: 214-665-6660

Superfund: 1-800-533-3508



